

## **Digital Multimeters/Clamp Meters/Voltage and Continuity Testers**

## **Selection Guide for DMM Accessories**

|     | Part<br>number |  | Target application   |   |   |   |   |   |   |   |   |   |   | MD 1150<br>MD 1050 |
|-----|----------------|--|--|---|---|---|---|---|---|---|---|---|---|--------------------|
| Ser | AMD<br>9023    | Thermocouple probe, type K                     | Probe for contact temperature measurement.   | ✓ | ✓ | - | ✓ | ✓ | ✓ | ✓ | ✓ | _ | - |                    |
| 11  | AMD<br>9024    | Adapter for<br>thermocouple probe<br>AMD 9023  | Adapter is intended to connect the thermocouple probe with a multimeter.   | ✓ | ✓ | _ | ✓ | ✓ | ✓ | ✓ | ✓ | _ | _ |                    |
| 100 | AMD<br>9025    | PC Software for MD<br>9015 with RS232<br>cable | Basic downloading software supplied on CD and RS232 communication cable.   | _ | _ | - | - | - | - | ✓ | ✓ | - | - |                    |
| 100 | AMD<br>9050    | USB interface set                              | Communication set contains USB adapter, USB and RS232 drivers and PC software on CD.                             | ✓ | ✓ | ✓ | _ | _ | - | - | _ | _ | - |                    |
| 100 | AMD<br>9240    | PC interface set for<br>MD 9240                | PC interface set enables data transferring to the PC. Set contains optical adapter, cable and PC software on CD. | _ | _ | - | ✓ | - | - | _ | _ | _ | ✓ |                    |
| 100 | AMD<br>9250    | PC interface set for<br>MD 9250                | PC interface set enables data transferring to the PC. Set contains optical adapter, cable and PC software on CD. | _ | - | - | _ | - | - | - | _ | ✓ | - |                    |
|     | AMD<br>1100    | Soft carrying bag                              | Small soft bag for storage of the multitester.   | _ | ı | - | - | - | - | _ | _ | - | - | <b>✓</b> ✓         |

Accessories: page 7.30

Not available